R12 DON'T Partially Support Stringers- Bottom

Possible
Fracture
Line