R7 DON'T cut beyond inside edge of bearing.